


# Introduction to the Lancair 360


## Mismatch of Drag Bucket in Cruise



**Airfoil Selection – NLF(1) 0215F**

# Introduction to the Lancair 360

Negative Flap setting relocates drag bucket & reduced pitching moment



**Airfoil Selection – NLF(1) 0215F**