


# SPEEDBRAKES


## LEFT BRAKE



EXTEND

COM  
RETRACT

## RIGHT BRAKE



2) AIRBRAKE MICRO SWITCHES SHOWN IN NC  
POSITION SO BRAKES ARE RETRACTING


3) THE HALL EFFECT SENSORS ARE NOT USED

28VDC

FAULT

GND


DB 25




NOTES :

1) POSITIVE VOLTAGE ON AIRBRAKE RETRACT TERMINAL  
RETRACT

28V




LEFT BRAKE




RIGHT BR

R 4



R 40-11D2-24



*TLM Designs*

SPDBRK

MOD: 4-2-1999\_8:10

DESIGN: TLM DRAWN: TLM SHEET OF